LIST OF TREES TO BE REMOVED FOR SUNRISE SOLAR / CLUB FIT BRIARCLIFF PROJECT					
No.	Size (dbh) & Species	Condition/Items of Note	Preserved or Removed		
1	10" Norway Maple	Poor health/NYS Invasive Tree/hazardous *	To be Removed		
2	10" Red Maple	Moderate health/potentially hazardous	To be Removed		
3	12" Maple	Moderate health/potentially hazardous	To be Removed		
4	18" Black Locust	Dead	To be Removed		
5	20" Unknown	Dead	To be Removed		
6	12" Black Locust	Poor health/NYS Invasive Tree/hazardous *	To be Removed		
7	20" Black Locust	Poor health/NYS Invasive Tree/hazardous *	To be Removed		
8	18" Black Locust	Poor health/NYS Invasive Tree/hazardous *	To be Removed		
9	18" Black Locust	Poor health/NYS Invasive Tree/hazardous *	To be Removed		
10	10" Norway Maple	Poor health/NYS Invasive Tree/hazardous *	To be Removed		
11	10" Norway Maple	Poor health/NYS Invasive Tree/hazardous *	To be Removed		
12	26" Black Locust	Poor health/NYS Invasive Tree/hazardous *	To be Removed		
13	28" Black Locust	Poor health/NYS Invasive Tree/hazardous *	To be Removed		
14	26" Black Locust	Poor health/NYS Invasive Tree/hazardous *	To be Removed		
15	8" Norway Maple	Moderate health/NYS Invasive Tree/potentally hazardous	To be Removed		
16	6"/8" Norway Maple	Poor health/NYS Invasive Tree/hazardous *	To be Removed		
17	18" Black Locust	Poor health/NYS Invasive Tree/hazardous *	To be Removed***		

* Due to proximity to targets (people, structures, powerlines, property) and defect(s) / evidence of poor health/decline likely to result in failure.

*** Outside proposed project limit of disturbance. Tree to be cut with stump to remain.

PROJECT: SUNRISE SOLAR SOLUTIONS	PREPARED BY:	DATE:	5–26–20
GROUND MOUNT SOLAR ARRAY	INSITE ENGINEERING, SURVEYING &	SCALE:	N. T. S.
584 NORTH STATE ROAD, TOWN OF OSSINING, WESTCHESTER CO., NY		PROJECT NO .:	20136.100
DRAWING:	LANDSCAPE ARCHITECTURE, P.C.	FIGURE:	
<u>LIST OF TREES TO BE REMOVED</u> (Attachment to 5-26-20 letter to building inspector)	3 Garrett Place • Carmel, New York 10512 Phone (845) 225–9690 • Fax (845) 225–9717 www.insite-eng.com		1