

Dale Cemetery Update




Maintenance Garage



Garage Area Before Cleanup



Unused Vehicles



Unused Vehicle



Old Truck Body Before Cleanup



Truck Body/Vehicle Removal





Village Sanitation Assisting in Garage Cleanup



Excavator Removal to Town Highway Dept.



Garage Lot Before Cleanup





Garage Progress



Garage Lot



Damaged Garage Siding



North Side Of Garage



Garage Siding Replacement




New Siding




Main House/Office

Office Building in need of paint/exterior repairs



Main House/Office





Tree work Removal of Large Limb in Lower 5



Tree work





Fence Primed and Painted



Children's Section East



Children's Section West






Preparing for Burial Section 5



Winter Burial



Old Section 7 Sign



Section Sign Replacement Project



Section Sign Replacement Example



New Bobcat Skid-Steer





Bobcat Skid Steer in the winter



3600 Utility Vehicle





Daily Visitors

